



GRAVEL PACK: N/A

CASING STICKUP: N/A

N/A

LOCATION MAP

PORSE
11.3.18.1
v6

See Figure 2

EASTING

Well Completion		Static Water Level	Moisture Content	PID Reading (ppm)	Penetration (blows/6")	Depth (feet)	Sample		Soil Type	LITHOLOGY / DESCRIPTION
Backfill	Casing						Recovery	Interval		
BENTONITE		<div>▽ 05/10/04</div>				1			GP	Gravel/Sand fill
						2			SP	Vacuum-Cleared Boring Location to 5 feet bgs. No Soil Characteristics Logged.
						3				
						4				
						5				
	Moist		0.1			6				Poorly graded SAND, brown 75% medium sand, 25% fine sand
						7				
						8				
						9				
	Moist		0.8			10				
						11				
						12				
						13				
	Moist		2			14				
	Wet		310			15			grades gray in color with trace wood debris	
						16				
						17				
						18				
	Moist		23.2			19			ML	SILT, gray, firm, moist 100% silt
						20				
						21				
						22				

USEPA SF



1288275